



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
DEVONSHIRE ROAD	O/S 57A	Dangerous	Significant stem cavity and crown dieback	Prunus sp	Plant in new 800mm pit in same position.	Sorbus 'Schouten'
DEVONSHIRE ROAD	O/S 73	Dangerous	Scaffold decaying, poor structural condition	Prunus serrula	Plant in new 800mm pit in same position.	Sorbus 'Schouten'
DEVONSHIRE ROAD	OPP 57A	Damaging	Kerb and edgings displaced by shallow roots	Prunus sp	Plant in existing pit opposite 57A (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
DEVONSHIRE ROAD	O/S 78A	Damaging	F/W uplifted and kerbs displaced	Prunus serrula	Plant in existing pit o/s 78A (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
DEVONSHIRE ROAD	O/S 86	Dangerous	Stem in c/w at <5.2m, obstructive	Sorbus intermedia	Plant in existing pit o/s 86 (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
DEVONSHIRE ROAD	O/S 90	Damaging	F/W uplifted and cracked by vigorous shallow roots	Prunus serrula	Plant in existing pit o/s 90 (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
DEVONSHIRE ROAD	o/s 67, (lowermost 1 of 2 trees o/s 67)	Damaging	F/W uplifted and cracked by vigorous shallow roots	Prunus sp	Plant in existing pit o/s 67, (equidistant between 2 adjacent trees), (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
DEVONSHIRE ROAD	O/S 63	Dead	dead	Prunus Sp	plant in verge o/s 63 (same as felled tree)	sorbus 'schouten'